

# PWCSA Hydrant Flow Report

## General Information

Location: 15000 Washington St  
Service Level: Haymarket  
High/Low HGL: 535 / 515

Date: 8-4-2017  
Time: 10:50 a.m.  
Test By: TR/KC

## Static Hydrant Information


Map Number: 091  
Manufacturer: Mueller  
Year Manufactured: 1997

Static Hydrant Number: 31  
Static Pressure: 71 psi  
Residual Pressure: 67 psi

## Flow Hydrant Information

Map Number: 091  
Manufacturer: Mueller  
Year Manufactured: 1997

Flow Hydrant Number: 30  
Flow Rate: 1220 gpm  
Pitot Pressure: 52 psi



\*\* The Prince William County Service Authority is not responsible for assumptions, calculations, or designs made based on the results of this test. Please note that the flows available from these hydrants are subject to changes or operational variations in the PWCSA's water system. You are requested to apply these results exercising professional judgment and employing the help of an accurate hydraulic computer model\*\*

Report generated on: August 4, 2017